
DESIGN STRESSES

## SCOPE OF WORK

- 1. Bridge Deck Hydro-scarification.
- 2. Repair bridge deck.
- 3. Repair approach slab.
- 4. Replace preformed joint seal with silicone joint seal at Piers 1 and 8.
- 5. Place new overlay.
- 6. Clean and reseal relief joints at the end of approach slabs.
- 7. Clean trough under fingerplate expansion joint at both abutments and Pier 5.
- 8. Apply concrete sealer to top inside face of parapets and abutment wingwalls, approach slabs, tops of Piers 1 and 8, abutment seats and abutment backwalls.




GENERAL PLAN AND ELEVATION 1 OF 3 I-290 WB OVER I-290 EB & I-355 DuPAGE COUNTY STATION 24+17 STRUCTURE NO. 022-0094


SHEE 8

ET NO. 1	F.A.I. RTE.	SEC <sup>-</sup>	LION		COUNTY	TOTAL SHEETS	SHEET NO.
	290 355	22(1, 1-1,	2&3)RS-	7	DUPAGE	546	358
SHEETS					CONTRACT	NO. 60	G51
	FED. ROA	AD DIST. NO.	ILLINOIS	FED.	AID PROJECT		

DATE: 11 16 09

## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION





ELEVATION

DESIGNED	-	ŢIJ
CHECKED	-	AAY
DRAWN	-	RMG
CHECKED	-	AAY

Existing Structure:

The structure is a nine-span continuous, composite plate girder structure with an 8 1/2-inch cast-in-place concrete deck and a 2-inch concrete overlay. The original structure was built in 1970 as FAI Route 90, Sections 22-1HB-5 & 22-1HB-8. In 1988, the bridge was widened, patched and overlaid, the approach slabs were patched, and the expansion joints were reconstructed. In 1998, the

Stage construction shall be utilized to maintain traffic during construction.

deck and the approach slabs were repaired.

No salvage

- Structure Location

LOCATION SKETCH

benesch

Engineers · Surveyors · Planners
205 North Michigan Averue, Suite 2400
Chicago, Illinois 8030 Job No. 10050